



Instruction Sheet

Pop-Up Power Tap




1. Hole Size In Required In Work Surface:




2. Installation Into Work Surface:


Note: Table thickness must be 3/4" up to 1-3/4"




Clamp orientation must be reversed for thicker tables.



Drop Pop-Up unit into hole in Work Surface.



Rotate each latch into position, and tighten down (do not over tighten).



Attach cord cable clamp with screw, to bottom of table.

3. Using The Pop-Up Power Tap

Push down center of unit, to lock down/release.

