


INTERFACE G2 UT INSTALLATION

Components & Hardware



A) Interface G2 UT, Qty. 1
(INT-UT-41U Shown)


Tools Needed




Note: Circuit breaker reset button located inside data compartment. A licensed electrician should make the hardware connections.

*Take care not to pierce finished surfaces.

- 1-** Locate and cut the hole for the Interface G2. Prepare pilot holes as needed.*



- 2-** Mount Interface G2 UT (A) beneath the cutout. Secure with screws* (not provided) and position as needed. Fabricate top as required.



- 3-** Connect all power and data cabling as needed.

- 4-** Connections for hardwire units:

Black wire – circuit hot
White wire – circuit neutral
Green wire – circuit ground