

DEKKO

7310 Innovation Blvd. Suite 104
Fort Wayne, IN 46818
Customer Service: 800.357.5622

TUCK

- Corded -

Worksurface Mounting
Installation Instruction


This device complies with part 15A of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Tools Required




1 Install TUCK Power Tap to TUCK Desktop Mounting Bracket with (2) Thumbscrews

* Rear of TUCK Power Tap Shown *




2 Install Bottom Bracket Under the Worksurface

* Underside of Worksurface *



3 Secure Thumb Screws and Route Power Cord Option to Nearest Power Distribution Source

* Underside of Worksurface *



E.C.N. No: GD23-3077

Part Number: G110449

Page Number: 1 of 1

Revision: A

POWER AND DATA

STUDIO

BY DEKKO