

COVE SM INSTALLATION

Components & Hardware



(A)Cove SM, Qty. 1

Tools Needed





For use with: This product fits tables .5" – 2" thick.

Note: * Take care not to pierce finished surfaces.

Installation Instructions:

- 1-** Determine the Cove SM's (A) mounting location and prepare the surface by cutting the mounting hole as shown.
- 2-** Insert the Cove SM through the cutout from above.
- 3-** While applying downward pressure on Cove from above, bend the side brackets up against the underside of the work surface (both sides). Ensure brackets sit flat against table after bend as shown.
- 4-** Optional – Screwing brackets to underside of surface provides additional mounting support (#8 wood screws - not provided). Insert screw through hole in tab and secure to underside of work surface as needed*.



Plug into an appropriate outlet that is properly installed and grounded in accordance with all local codes and regulations.