



7310 Innovation Blvd. Suite 104
Fort Wayne, IN 46818
Customer Service: 800.357.5622

ELECTROLITE UT MOUNT


Corded
Under Worksurface Positioning
[Installation Instruction](#)

This device complies with part 15A of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



Tools Required _____



1 Install clamp mount to bottom of ELECTROLITE assembly.




ELECTROLITE
UT MOUNT




ELEVATION
DETAIL

2 Position ELECTROLITE UT MOUNT unit in desired location under worksurface and secure it with (2) #10 X .75in screws.



#10 X .75
Screws
(2-Req'd)



3 Route power cord option to nearest power distribution source and manage extra cordage with mounting clamps.

* NOTE *

Plug into an appropriate outlet that is properly installed and grounded in accordance with all local codes and regulations.

(Optional)
Power Cord
Mounting Clamps
and Screws Not Included

